

XH Hydraulic Pressure /Force Gauges



CBM

Center back mount



CBMFF

Center back mount
with front frange



LM

Lower mount




LMBF

frange back
with mount Lower



-M

Max. Indicator
Pointer



Pressure range : 0~15,000psi
Accuracy : ±1%

How is a hydraulic pressure gauge model number is built up:

X H O 2 . 5 C B M F F 2 P 1 K - M

1 2 3 4 5 6

1. Gauge style

O=Oil
V=Vacuum(no stock)

2. Face

2.5=2.5"
4=4"
6=6"

3. Connect style

CBM= Center back mount
CBMFF= Center back mount
with front frange
LM= Lower mount
LMBF= Frange back with mount
lower

4. Connect thread

2P=1/4PT
2N=1/4NPT
3P=3/8PT
3N=3/8NPT
4P=1/2PT
4N=1/2NPT

5. Pressure range

1,000 for count radix
and then show unit
30P=30,000psi
1K=1,000kg
1B=1,000bar
0.15K=150kg

6. Special

M=Max. Indicator
pointer

Model Number	Face (mm)	Style	Connect thread	Pressure range
XHO2.5CBMFF2P1K	60	Center back mount with front fringe	1/4PT	0~1,000kgf/cm ²
XHO2.5LM2N1B	60	Lower mount	1/4NPT	0~1,000bar
XHO2.5LM2N1K	60	Lower mount	1/4NPT	0~1,000kgf/cm ²
XHO2.5LM2P0.15K	60	Lower mount	1/4PT	0~150kgf/cm ²
XHO2.5LM2P1K	60	Lower mount	1/4PT	0~1,000kgf/cm ²
XHO2.5LM2P0.7K-M	60	Max. Indicating pointer	1/4PT	0~700kgf/cm ²
XHO4CBM2P0.7K	100	Center back mount	1/4PT	0~700kgf/cm ²
XHO4CBM2P1K	100	Center back mount	1/4PT	0~1,000kgf/cm ²
XHO4CBM3P1K	100	Center back mount	3/8PT	0~1,000kgf/cm ²
XHO4CBMFF3P0.35K	100	Center back mount	3/8PT	0~350kgf/cm ²
XHO4CBMFF3P0.4K	100	Center back mount	3/8PT	0~400kgf/cm ²
XHO4LM2N1B	100	Lower mount	1/4NPT	0~1000bar
XHO4LM3P0.15K	100	Lower mount	3/8PT	0~150kgf/cm ²
XHO4LM3P0.25K	100	Lower mount	3/8PT	0~250kgf/cm ²
XHO4LM3P0.35K	100	Lower mount	3/8PT	0~350kgf/cm ²
XHO4LM3P1K	100	Lower mount	3/8PT	0~1,000kgf/cm ²
XHO4LM3P0.15K-M	100	Max. Indicating pointer	3/8PT	0~150kgf/cm ²
XHO4LM3P0.1K-M	100	Max. Indicating pointer	3/8PT	0~100kgf/cm ²
XHO4LM3P0.25K-M	100	Max. Indicating pointer	3/8PT	0~250kgf/cm ²
XHO4LM3P0.35K-M	100	Max. Indicating pointer	3/8PT	0~350kgf/cm ²
XHO4LM3P0.5K-M	100	Max. Indicating pointer	3/8PT	0~500kgf/cm ²
XHO4LM3P0.7K-M	100	Max. Indicating pointer	3/8PT	0~700kgf/cm ²
XHO4LM3P1K-M	100	Max. Indicating pointer	3/8PT	0~1,000kgf/cm ²
XHO6LMBF4N30P	100	Lower mount with back fringe	1/2NPT	0~30000psi

XHD

Digital, Hydraulic Force & Pressure Gauges

Power : AC110~220V
Accuracy : ±0.2%
Pressure range 15,000 psi.
Displays in psi , bar, Map,
kg, lb..or user order.



Model Number	Description	Pressure range (psi)
XHD-1	Max. Indicating keep	0~15,000
XHD-2	Max. Indicating not keep	0~15,000